

IECEx Quality Assessment Report Summary

Valid until: 2022-02-28

Audit date: 2019-02-28

INTERNATIONAL ELECTROTECHNICAL COMMISSION **IEC Certification System for Explosive Atmospheres**

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: ES/LOM/QAR16.0002/02 Page 1 of 1

QAR Free Ref. No.: LOM 19.04222 Status: Issued

Re-Assessment audit and include types of protection Details of change: Date of issue: 2019-08-29

flameproof enclosure "d", encapsulation "m" and intricsic

safety "i"

Site(s) audited: Delvalle Global Solutions, S.L.U. Paso El Prao, 6. 01320,

Oyón. Alava. Spain.

Issuing ExCB: LOM - Laboratorio Oficial J.M. Madariaga (LOM)

Manufacturer: Delvalle Global Solutions, S.L.U.

Paso El Prao, 6. 01320, Óyón. Alava. Spain.

Location of

Manufacturer:

Spain

Product information: Empty boxes, connection boxes and control stations.

Increased safety "eb", protection by enclosure "tb", intrinsic safety "i" (Ex ia/ib), flameproof enclosure "db" Protection concept:

and encapsulation "mb".

Related QARs:

ES/LOM/QAR16.0002/00

ES/LOM/QAR16.0002/01

Related Certificates (manual insertion):

IECEx CML 19.0079U issue: 0 Related Certificates

(automatic linking): IECEx CML 19.0080U issue: 0

IECEx CML 19.0081U issue: 0 IECEx CML 19.0082U issue: 0 IECEx CML 19.0088X issue: 0 IECEx CML 19.0084U issue: 0 IECEx CML 19.0085U issue: 0 IECEx CML 19.0086U issue: 0 IECEx CML 19.0087X issue: 0

IECEx CML 19.0083U issue: 0

Related Certificates for previous versions:

IECEx LOM 16.0002U issue: 0 IECEx LOM 16.0002U issue: 1 IECEx LOM 16.0003U issue: 0 IECEx LOM 16.0004U issue: 0 IECEx LOM 16.0003U issue: 1 IECEx LOM 16.0004U issue: 1

IECEx LOM 18.0001X issue: 0

Comments: